July 19, 2005 9704-PFS-107

DOCUMENT CONTROL DESK UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D.C. 20555

Reference:

- a) Boeing Letter G-1151-RSO-92-365 dated August 31, 1992; R.S.
 - Orr to the NRC Operations Center
- b) NRC Letter Docket No. 99901227 dated August 12, 1992; L. J. Norrholm to R. S. Orr; Subject: Response to 10 CFR 21 Inquiry

Dear Sir or Madam:

In accordance with the Reference correspondence and 10 CFR 21, Boeing is sending the NRC the attached error notices received from our former software suppliers. Because of unknown current addresses, the following former customers were not notified:

Reactor Controls, Inc
Echo Energy Consultants
Nuclear Applications and Systems Analysis Company (Japan)
Nuclear Power Services
GPU Nuclear Corporation
Tenera, Inc.
Stone & Webster Engineering
Raytheor Engineers & Constructors
Gilbert Associates, Inc.

Error notices have been sent to our other former customers.

Very truly yours,

Pat Soroe

Nuclear Administrator

(425) 865-5386

patricia.f.soroe@boeing.com

Enclosures: GT STRUDL Program Report Forms 2005.02 – 2005.04

TE20

GPRF No.: <u>2005.02</u>

DATE: 6/15/05

FROM:

Computer-Aided Structural Engineering Center

Georgia Institute of Technology Atlanta, Georgia 30332-0355

| SEVERITY LEVE |
|---------------|
|---------------|

| X URGENT | Problem results in incorrect answers which may not be apparent or job aborts and cannot be recovered within the session or job. | | |
|--|---|--|--|
| _ SERIOUS | Problem results in incorrect answers which are obvious or problem prevents completion of a particular user's task. | | |
| _MINOR | Problem can be worked around or problem poses high frustration factor. | | |
| _ INFORMATIVE | Documentation error, program usage tip, user inconveniences. | | |
| Date Problem Confirmed _ | June 9, 2005 | | |
| Date Notification Sent | 6/15/05 | | |
| Computers All | | | |
| Operating System All | | | |
| Version All | | | |
| Target Release for Correcti | | | |
| Mudulf Starge. Signature | Sr. RE Title | | |
| R & D Division | | | |
| Michael H. Swanger Typed or Printed Name | Date of Signature | | |
| Dand C. Key Signature | Configuration Control Manager Title | | |
| Professional Services Divis | | | |
| David C. Key | 6/15/0 S | | |
| Typed or Printed Name | Date of Signature | | |

GTSTRUDL Program Report Form (Continued)

GPRF No.: <u>2005.02</u>

DATE: 6/15/05

DESCRIPTION:

GTSTRUDL static and dynamic analyses will abort if member releases are specified for rigid bodies (TYPE RIGID PLANE/PLATE/PIN/SOLID). Member releases may be specified only for plane and space frame members. Rigid members that have member releases, or other special member end conditions such as member eccentricities and end joint sizes, are more appropriately modeled by plane/space frame members with large stiffness properties to model the rigid behavior.

GTSTRUDL Reference Manual Sections

Joint Constraints - Rigid Bodies and Joint Ties

Section 2.6.5, Volume 3

Computer-Aided Structural Engineering Center

GPRF No.: 2005.03

DATE: 6/20/05

Georgia Institute of Technology Atlanta, Georgia 30332-0355 **SEVERITY LEVEL:** Problem results in incorrect answers which may not be apparent URGENT · or job aborts and cannot be recovered within the session or job. Problem results in incorrect answers which are obvious or SERIOUS problem prevents completion of a particular user's task. X MINOR Problem can be worked around or problem poses high frustration factor. Documentation error, program usage tip, user inconveniences. INFORMATIVE Date Problem Confirmed June 16, 2005 Date Notification Sent 6/20/05 Computers All Operating System All Version All Target Release for Correction Version 29.0 Signature Title R & D Division Michael H. Swanger Typed or Printed Name Configuration Contal Manager Signature **Professional Services Division** Typed or Printed Name

FROM:

GTSTRUDL Program Report Form (Continued)

GPRF No.: <u>2005.03</u>

DATE: 6/20/05

DESCRIPTION:

The execution of the FORM MISSING MASS command assumes that the DAMPING RATIO/PERCENT is 0.0 if neither of the words RATIO or PERCENT is given in the command following the DAMPING option. The following message will be reported if neither of the words RATIO or PERCENT is given in the command and the assumed damping ratio of 0.0 is not within the range of the damping values for the response spectrum curve(s) of the specified response spectrum loading:

```
{ 6151} > FORM MISSING MASS LOAD 'MM103' -
{ 6152} > FROM RESPONSE SPECTRA LOAD 103 FREQ 33.00 DAMPING 0.05

**** ERROR_STDZPA -- DAMPING RATIO FOR MISSING MASS LOAD COMPUTATION
LIES OUTSIDE THE RANGE OF SPECTRAL CURVES FOR
RESPONSE SPECTRUM LOAD 103 . SCAN MODE ENTERED.

CI-w-cmdnpro, ERROR: The following symbols were not processed.
0.05
```

If the assumed damping ratio of 0.0 is within the range for the response spectrum curve(s) of the specified response spectrum loading, then the following error message is reported and the missing mass loading is computed for a damping ratio of 0.0:

```
{ 6151} > FORM MISSING MASS LOAD 'MM103' -
{ 6152} > FROM RESPONSE SPECTRA LOAD 103 FREQ 33.00 DAMPING 0.05
CI-w-cmdnpro, ERROR: The following symbols were not processed.
0.05
```

However, this situation can occur only if one of the response spectrum curve(s) of the specified response spectrum loading has a damping ratio/percent of 0.0.

In order to correct this error condition, add the appropriate word, either RATIO or PERCENT, to the FORM MISSING MASS command following the word DAMPING:

```
FORM MISSING MASS LOAD 'MM103' -
FROM RESPONSE SPECTRA LOAD 103 FREQ 33.00 DAMPING RATIO 0.05
```

GTSTRUDL Reference Manual Sections

The FORM MISSING MASS Command

Section 2.4.9.1, Volume 3

GPRF No.: $\frac{2005.4}{1/05}$

1

FROM: Computer-Aided Structural Engineering Center

Georgia Institute of Technology Atlanta, Georgia 30332-0355

SEVERITY LEVEL:

| X URGENT | Problem results in incorrect answers which be recovered within the session or job. | may not be apparent or job aborts and cannot | |
|---|--|--|--|
| _ SERIOUS | Problem results in incorrect answers which are obvious or problem prevents completion of a particular user's task. | | |
| _MINOR | Problem can be worked around or problem | poses high frustration factor. | |
| _INFORMATIVE | Documentation error, program usage tip, us | er inconveniences. | |
| Date Problem Confirmed | | | |
| Date Notification Sent | 7/1/05 | · | |
| Computers ALL | | | |
| Operating System <u>ALL</u> | <u>′ </u> | | |
| Version Version 87.01 Signature R & D Division | through and including version 28 | Senior Software Engineer Title | |
| Hamid Zand Typed or Printed Name | | Sune 30, 2005 Date of Signature Configuration Control Manager | |
| Signature Professional Services Divi | sion | Configuration Control Manager Title | |
| David C. Keg Typed or Printed Name | | 7/1/05 Date of Signature | |

(Continued)

GPRF No.: 2005. 04

DATE: 7/1/05

DESCRIPTION:

Applicable GTSTRUDL Command:

Steel design CHECK or SELECT MEMBERS command

Applicable GTSTRUDL Steel Design Function:

Automatic K-factor computation


GTSTRUDL Documentation Reference:

Sections 2.2 and 2.3 of Volume 2A

Explanation:

Automatic K-factor computations will be incorrect if the user specifies parameter FRLY or FRLZ for the beams or columns connected to the member for which the K-factor is being computed.

Example:



COLUMN LINE 'COL1' MEMBERS 1 TO 3

PARAMETERS

FRLY 0.5 MEMBERS 4 TO 9 COMPK KZ MEMBERS 1 TO 3

OR if problem is a 3D model

COMPK YES MEMBERS 1 TO 3

CHECK MEMBERS 1 TO 3

OR

SELECT MEMBERS 1 TO 3

Workaround:

Specify the parameters LY and LZ for the unbraced length. Do not use FRLY and FRLZ when requesting the automatic K-factor computation.

Important Note:

The problem with parameters FRLY and FRLZ only affects the automatic K-factor computation. Parameters FRLY and FRLZ are correctly implemented for all other steel design code check or select commands.

Rev. 2.5